

$S_p = 4,6 \text{ mA/V}$
 $R_i = 750 \text{ k}$
 $P_a = \text{max. } 2 \text{ W}$

$S_T = 5,8 \text{ mA/V}$
 $R_i = 6,9 \text{ k}$
 $\mu = 40$
 $P_a = \text{max. } 1 \text{ W}$

