

A
 $S = 4,4 \text{ mA/V}$
 $\mu = 18$
 $R_i = 4,1 \text{ k}$
 $P_a = \text{max. } 5,5 \text{ W}$

B
 $S = 2 \text{ mA/V}$
 $\mu = 20$
 $R_i = 11 \text{ k}$
 $P_a = \text{max. } 1,25 \text{ W}$

